

MSP430FR573x, MSP430FR572x Device Erratasheet

1 Current Version

See [Appendix A](#) for prior silicon revisions.


✓ The checkmark means that the issue is present in the specified revision.

Device	Rev:	CPU40	EEM19	MPY1	PORT16
MSP430FR5720	H	✓	✓	✓	✓
MSP430FR5721	H	✓	✓	✓	✓
MSP430FR5722	H	✓	✓	✓	✓
MSP430FR5723	H	✓	✓	✓	✓
MSP430FR5724	H	✓	✓	✓	✓
MSP430FR5725	H	✓	✓	✓	✓
MSP430FR5726	H	✓	✓	✓	✓
MSP430FR5727	H	✓	✓	✓	✓
MSP430FR5728	H	✓	✓	✓	✓
MSP430FR5729	H	✓	✓	✓	✓
MSP430FR5730	H	✓	✓	✓	✓
MSP430FR5731	H	✓	✓	✓	✓
MSP430FR5732	H	✓	✓	✓	✓
MSP430FR5733	H	✓	✓	✓	✓
MSP430FR5734	H	✓	✓	✓	✓
MSP430FR5735	H	✓	✓	✓	✓
MSP430FR5736	H	✓	✓	✓	✓
MSP430FR5737	H	✓	✓	✓	✓
MSP430FR5738	H	✓	✓	✓	✓
MSP430FR5739	H	✓	✓	✓	✓

2 Package Markings



DA38

TSSOP (DA), 38 Pin

 YMLLLLS# M430FRxxxx G4 ○	YM = Year and Month Date Code LLLL = LOT Trace Code S = Assembly Site Code # = DIE Revision o = PIN 1
---	---

PW28

TSSOP (PW), 28 Pin

4FRxxxx  YMS # ○ LLLL	YM = Year and Month Date Code LLLL = LOT Trace Code S = Assembly Site Code # = DIE Revision o = PIN 1
MSP430FRxxxx  YMS G4 ○ LLLL #	YM = Year and Month Date Code LLLL = LOT Trace Code S = Assembly Site Code # = DIE Revision o = PIN 1

RGE24

QFN (RGE), 24 Pin

○ M430FR xxxxx TI YMS LLLL #	YM = Year and Month Date Code LLLL = LOT Trace Code S = Assembly Site Code # = DIE Revision o = PIN 1
---------------------------------------	---

RHA40

QFN (RHA), 40 Pin

○ M430 FRxxxx TI # YMS LLLLG4	YM = Year and Month Date Code LLLL = LOT Trace Code S = Assembly Site Code # = DIE Revision o = PIN 1
--	---

3 Detailed Bug Description

CPU40

CPU Module

Function

PC is corrupted when executing jump/conditional jump instruction that is followed by instruction with PC as destination register or a data section

Description

If the value at the memory location immediately following a jump/conditional jump instruction is 0X40h or 0X50h (where X = don't care), which could either be an instruction opcode (for instructions like RRCM, RRAM, RLAM, RRUM) with PC as destination register or a data section (const data in flash memory or data variable in RAM), then the PC value is auto-incremented by 2 after the jump instruction is executed; therefore, branching to a wrong address location in code and leading to wrong program execution.

For example, a conditional jump instruction followed by data section (0140h).

```
@0x8012  Loop      DEC.W R6
@0x8014          DEC.W R7
@0x8016          JNZ Loop
@0x8018  Value1    DW 0140h
```

Workaround

In assembly, insert a NOP between the jump/conditional jump instruction and program code with instruction that contains PC as destination register or the data section.

EEM19

Enhanced Emulation Module

Function

DMA may corrupt data in debug mode

Description

When the DMA is enabled and the device is in debug mode, the data transferred by the DMA may be corrupted when a breakpoint is hit or when the debug session is halted.

NOTE: This erratum applies to debug mode only.

Workaround

None. Do not set a breakpoint during a DMA transfer.

MPY1

Hardware Multiplier (MPY) Module

Function

Save and Restore feature on MPY32 not functional

Description

The MPY32 module uses the Save and Restore method which involves saving the multiplier state by pushing the MPY configuration/operand values to the stack before using the multiplier inside an Interrupt Service Routine (ISR) and then restoring the state by popping the configuration/operand values back to the MPY registers at the end of the ISR. However due to the erratum the Save and Restore operation fails causing the write operation to the OP2H register right after the restore operation to be ignored as it is not preceded by a write to OP2L register resulting in an invalid multiply operation.

Workaround

None. Disable interrupts when writing to OP2L and OP2H registers.

NOTE: When using the C-compiler, the interrupts are automatically disabled while using the MPY32.

PORT16
Digital I/O Module
Function

GPIO pins are driven low during device start-up

Description

During device start-up, all of the GPIO pins are expected to be in the floating input state. Due to this erratum, some of the GPIO pins are driven low for the duration of boot code execution during device start-up, if an external reset event (via the $\overline{\text{RST}}$ pin) interrupted the previous boot code execution. Boot code is always executed after a BOR, and the duration of this boot code execution is approximately 500 μs .

For a given device family, this erratum affects only the GPIO pins that are not available in the smallest package device family member, but that are present on its larger package variants.

NOTE: This erratum does not affect the smallest package device variants in a particular device family.

Workaround

Ensure that no external reset is applied via the $\overline{\text{RST}}$ pin during boot code execution of the device, which occurs 1 μs after device start-up.

NOTE: System application needs to account for this erratum to ensure that there is no increased current draw by the external components or damage to the external components in the system during device start-up.

Appendix A Prior Versions

✓ The checkmark means that the issue is present in the specified revision.

Device	Rev:	CPU40	EEM19	MPY1	PORT16
MSP430FR5720	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5721	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5722	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5723	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5724	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5725	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5726	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5727	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5728	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5729	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5730	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5731	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5732	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5733	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓

Device	Rev:	CPU40	EEM19	MPY1	PORT16
MSP430FR5734	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5735	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5736	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5737	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5738	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓
MSP430FR5739	F	✓	✓	✓	✓
	G	✓	✓	✓	✓
	H	✓	✓	✓	✓

Revision History

Changes from A Revision (October 2011) to B Revision	Page
• Added silicon revisions G and H	1

NOTE: Page numbers for previous revisions may differ from page numbers in the current version.

IMPORTANT NOTICE

Texas Instruments Incorporated and its subsidiaries (TI) reserve the right to make corrections, modifications, enhancements, improvements, and other changes to its products and services at any time and to discontinue any product or service without notice. Customers should obtain the latest relevant information before placing orders and should verify that such information is current and complete. All products are sold subject to TI's terms and conditions of sale supplied at the time of order acknowledgment.

TI warrants performance of its hardware products to the specifications applicable at the time of sale in accordance with TI's standard warranty. Testing and other quality control techniques are used to the extent TI deems necessary to support this warranty. Except where mandated by government requirements, testing of all parameters of each product is not necessarily performed.

TI assumes no liability for applications assistance or customer product design. Customers are responsible for their products and applications using TI components. To minimize the risks associated with customer products and applications, customers should provide adequate design and operating safeguards.

TI does not warrant or represent that any license, either express or implied, is granted under any TI patent right, copyright, mask work right, or other TI intellectual property right relating to any combination, machine, or process in which TI products or services are used. Information published by TI regarding third-party products or services does not constitute a license from TI to use such products or services or a warranty or endorsement thereof. Use of such information may require a license from a third party under the patents or other intellectual property of the third party, or a license from TI under the patents or other intellectual property of TI.

Reproduction of TI information in TI data books or data sheets is permissible only if reproduction is without alteration and is accompanied by all associated warranties, conditions, limitations, and notices. Reproduction of this information with alteration is an unfair and deceptive business practice. TI is not responsible or liable for such altered documentation. Information of third parties may be subject to additional restrictions.

Resale of TI products or services with statements different from or beyond the parameters stated by TI for that product or service voids all express and any implied warranties for the associated TI product or service and is an unfair and deceptive business practice. TI is not responsible or liable for any such statements.

TI products are not authorized for use in safety-critical applications (such as life support) where a failure of the TI product would reasonably be expected to cause severe personal injury or death, unless officers of the parties have executed an agreement specifically governing such use. Buyers represent that they have all necessary expertise in the safety and regulatory ramifications of their applications, and acknowledge and agree that they are solely responsible for all legal, regulatory and safety-related requirements concerning their products and any use of TI products in such safety-critical applications, notwithstanding any applications-related information or support that may be provided by TI. Further, Buyers must fully indemnify TI and its representatives against any damages arising out of the use of TI products in such safety-critical applications.

TI products are neither designed nor intended for use in military/aerospace applications or environments unless the TI products are specifically designated by TI as military-grade or "enhanced plastic." Only products designated by TI as military-grade meet military specifications. Buyers acknowledge and agree that any such use of TI products which TI has not designated as military-grade is solely at the Buyer's risk, and that they are solely responsible for compliance with all legal and regulatory requirements in connection with such use.

TI products are neither designed nor intended for use in automotive applications or environments unless the specific TI products are designated by TI as compliant with ISO/TS 16949 requirements. Buyers acknowledge and agree that, if they use any non-designated products in automotive applications, TI will not be responsible for any failure to meet such requirements.

Following are URLs where you can obtain information on other Texas Instruments products and application solutions:

Products

Audio	www.ti.com/audio
Amplifiers	amplifier.ti.com
Data Converters	dataconverter.ti.com
DLP® Products	www.dlp.com
DSP	dsp.ti.com
Clocks and Timers	www.ti.com/clocks
Interface	interface.ti.com
Logic	logic.ti.com
Power Mgmt	power.ti.com
Microcontrollers	microcontroller.ti.com
RFID	www.ti-rfid.com
OMAP Mobile Processors	www.ti.com/omap
Wireless Connectivity	www.ti.com/wirelessconnectivity

Applications

Automotive and Transportation	www.ti.com/automotive
Communications and Telecom	www.ti.com/communications
Computers and Peripherals	www.ti.com/computers
Consumer Electronics	www.ti.com/consumer-apps
Energy and Lighting	www.ti.com/energy
Industrial	www.ti.com/industrial
Medical	www.ti.com/medical
Security	www.ti.com/security
Space, Avionics and Defense	www.ti.com/space-avionics-defense
Video and Imaging	www.ti.com/video

TI E2E Community Home Page

e2e.ti.com

Mailing Address: Texas Instruments, Post Office Box 655303, Dallas, Texas 75265
Copyright © 2012, Texas Instruments Incorporated